COMPLETION REPORT

1. Name of Work : **IMPROVEMENTS TO ROAD MEI LAYOUT 11TH, 13TH, 14TH MAIN ROAD AND OTHER CROSS RODAS IN BAGALAGUNTE IN WARD NO. 14**

2. Sanctioned Estimate No. & Dt : ಟಿಇಒಸಿ/ಡಿ2/103/12-13 dt 8-8-2012

3. Head of Account which is Chargeable : PCI 2978

4. Work Order No. & Dt : ಆಪ/1001/ 12-13 dt

5. Name of Contractor : **TECHNICAL MANGER (WEST), KRIDL**

6a. Time stipulated for completion of work :

b. Delay in execution of work : --

7. Measurement recorded in : M.B. No. SBD/12-13

8. Check measurement of the Asst. : M.B. No. ..... Page No. 58623 to 58631

Asst. Exe. Eng. / Exe. Eng :

9. Name of the Office / Official : Page No. .....

incharge of the work :

10. a) Asst. Engineer ಡಿ.ಎಸ್.ಬಂಡಿಗಣಿ

b) Asst. Exe. Engineer ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು

Sanctioned estimated amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
SD ನಂ	4989053ನಂ	—	947ನಂ

CE/ACs 16/8/13

1) Certified that the above work has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER
W14

ASST. EXECUTIVE ENGINEER 26/9/13
SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Division, Bangalore-57.

ACCOUNTS SUPTD. ( )